



Carbamates by HPLC  
Analysis Report

Address: 1100 W 49th St  
Austin, TX 78756  
Mail: PO Box 149347, MC-1947  
Austin, TX 78714-9347  
envsciadmin@dshs.texas.gov  
www.dshs.state.tx.us  
512-776-7587

Texas Department of State  
Health Services

ENTERED

SCANNED

Submitter ID # (PWS ID #): 1870034

CANYON PARK WSC  
SIMARD, ROBERT  
PO BOX 1928  
ONALASKA, TX 77360-1928

Date Reported : 09/17/2024  
Report ID# : 20240917121416AG96206

Lab Sample ID# : AG96206  
Sample Priority : NORMAL  
TCEQ Sample ID: 2419646  
Water Source :  
Entry Point(s) : EP001

Date Collected : 08/20/2024 10:08  
Date Received : 08/21/2024  
Date Analyzed : 08/28/2024  
Conc. Units : µg/L  
Method : EPA Method 531.1  
Analyst : KP  
Sample Cond. : Acceptable

Regulated Compounds	Result	Qualifier
Aldicarb <sup>1</sup>	<0.5	
Aldicarb sulfone <sup>1</sup>	<0.8	
Aldicarb Sulfoxide <sup>1</sup>	<0.5	
Carbofuran <sup>1</sup>	<0.9	
Oxamyl <sup>1</sup>	<2.0	
Monitored Compounds	Result	Qualifier
Baygon	<2.0	
Carbaryl	<2.0	
3-Hydroxycarbofuran	<2.0	
Methiocarb	<4.0	
Methomyl	<2.0	

Comments:

The test results on this report relate only to the sample identified on this report. The test results for analytes noted(<sup>1</sup>) meet all TNI (2016 Standard) requirements.

Authorized by Team Lead JHE on 09/12/2024